

Oil Field Environmental Incident Summary

Incident: 20140315222845

Date/Time of Notice: 03/15/2014 22:28

Responsible Party: Eric

Well Operator:

Well Name:

Field Name: MCGREGOR

Well File #:

Date Incident: 3/15/2014

Time Incident: 11.00

Facility ID Number:

County: DIVIDE

Twp: 130

Rng: 60

Sec: 1

Qtr:

Location Description: From 96th st to 93rd st west to

Submitted By: Brett Finnicum

Received By:

Contact Person: Brett Finnicum
Hagstrom
sidney
sidney, mt 59270

General Land Use: Other - Described Above

Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident Valve/Piping Connection Leak

Release Contained in Dike No

Reported to NRC: Unknown

	Spilled	Units	Recovered	Units	Followup	Units
--	---------	-------	-----------	-------	----------	-------

Oil

Brine	5	Barrels				
-------	---	---------	--	--	--	--

Other

Description of Other Released Contaminant:

Production water from down hole.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

After driving the route of the spill there where no immediate risks of any kind.

Areal Extent:

There was approx. 5bbls of fluid leaked out of hose while driving down the gravel roads to disposal

Potential Environmental Impacts:

Very minimal environmental risk do to all fluid being on the road way in small amounts.

Action Taken or Planned:

Brought in company spill trailer in to clean up the bigger areas and took the right actions for proper disposal. Immediate termination of driver due to breaking company policies and safety regulations.

Wastes Disposal Location: There was minimum recover do to the fact that the road absorbed 90% of spill so you could not see where the spill occurred. Material that was recovered was taken to oaks disposal.

Agencies Involved: Local Law Enforcement

Updates

Date: 3/17/2014 **Status:** Reviewed; Followup Required **Staff:** Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill impacted areas off of an E & P location. Followup is necessary.

Date: 3/18/2014 **Status:** Inspected; More Followup Required **Staff:** O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Arrived at meeting location with Burke/Divide Deputy Sheriff at 13:00, 3/18/14. 30 degrees F, cloudy, NW wind 20-25 mph. Followed deputy sheriff to violation location, which was the ending location for the release. The location was on a gravel road (County Road 6). According to the deputy sheriff, the release started near a well pad, traveling north on 96th Avenue NW, turning west on 93rd Street NW, then north on 98th Avenue NW and ending turning west on County Road 6. The release extended approximately 6 miles. Two samples were collected from the surface of the gravel roads -- one from the deputy stop location and one from the surface of 96th Avenue NW, near the well pad. Follow up when lab results are received.